







FDA Introduction

















FDA Introduction







Data Into Perspective

Challenge The Read-Outs







Manual of Flight Data Analysis Programmes

ICAO Doc 10000 / 1st Ed 2014



"an FDAP may be described as a **non-punitive programme** for the routine collection and analysis of flight data to develop objective and predictive information **for advancing safety**".


Why a non-punitive programme?



Runway Overrun

Precursors

- + Late Descent
- + Too High
- + Too Fast
- + Long Flare
- + Landing after an unstabilized Approach





Runway Overrun

Contributing Factors

- + Fatigue
- + No Crew Communication
- + No Crew Coordination
- + F/O Lack of Assertiveness
- Many Pitch and Thrust adjustments during the flare

Latent Handling Problem?



Runway Overrun

Handling Skill

+ No reported training issue

Recent Crew Interview

+ Called for a Hard Landing



Safety Policy

The "Three Strikes Law" in force at that airline

Three Hard Landings



You are Fired

Contributing Factor



Hard Landing

Hazard Identification

+ Numerous **High Vertical G at Landing** FDA event

Mitigation Action

+ Put **Fine** on Captain triggering an event

Monitoring the Effectiveness

+ Less High vertical G at landing after few months

Safety Improvement?



Hard Landing Side Effects

- + No more landing by FO
- + Increase number of **Long Flare distance** FDA events
- + Flying the Software
- + Killing Voluntary reporting

A Non-Punitive Programme







Hard Landing

- We do not monitor Hard Landings
- We monitor High Vertical G at Landing

Goal:

- To Identify Handling Issue at Landing
- To Prevent Hard Landing



High Vertical G at Landing

- High Vertical G at Landing Triggering Values
 - VRTG > 1.50 G → Low Severity Event
 - VRTG > 1.60 G → Medium Severity Event
 - VRTG > 1.75 G → High Severity Event
- A320 Vertical G Hard Landing Threshold = 2.6 G

A High severity event "High Vertical G at Landing" is **NOT** a hard landing as per the maintenance definition.



High Vertical G at Landing

An FDA Tool is Not a Maintenance Tool

To Identify Trends

Predictive Safety Management



Hard Landing Risk

Precursors


- + Path High at Landing (below 20ft)
- + Vertical Speed High before touchdown
- + Pitch and/or Roll Cycling at Landing
- + Pitch High at Landing
- + Speed Low
- + etc.







Speed Above VFE





Speed Above VFE

Recording Limitation

- + VFE not recorded
- + Flaps lever position not recorded
- + Configuration not recorded


Solution

+ Slats and Flaps Angles



Speed Above VFE

To Sum up to get the VFE



Speed Above VFE

Issue

- Slats & Flaps Angles at the next configuration position to get the right VFE
- On board VFE is linked with the Flaps Lever Position


Consequence


Delay in updating the VFE

Solution

Call the right parameter







Event Investigation

Requirements

- Investigation without delay
- Competent FDA team member
- Ability to challenge in order to validate the results

Risks

- Loss of time on wrong events
- Focussing at finding solutions on unexisting issue
- Loss of Confidence in the FDA programme by the crew



Conclusion

Fundamentals for FDAP Efficiency

A Non-Punitive Programme

- + De-identification process Confidentiality
- + Safety Policy promoting a just culture endorsed by the Management

Competent FDA Team Members

- + A Critical Eye
- + Put the data into perspective
- + Able to challenge the results

Improving Safety



© Airbus S.A.S. All rights reserved. Confidential and proprietary document. This document and all information contained herein is the sole property of AIRBUS. No intellectual property rights are granted by the delivery of this document or the disclosure of its content. This document shall not be reproduced or disclosed to a third party without the express written consent of AIRBUS S.A.S. This document shall not be used for any purpose other than that for which it is supplied. The statements made herein do not constitute an offer. They are based on the mentioned assumptions and are expressed in good faith. Where the supporting grounds for these statements are not shown, AIRBUS S.A.S. will be pleased to explain the basis thereof. AIRBUS, its logo, A300, A310, A318, A319, A320, A321, A330, A340, A350, A380, A400M are registered trademarks.

